A DORMAN EXCLUSIVE CATEGORY



FLUID RESERVOIRS COVERAGE GUIDE



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES





COMPLETE RESERVOIR IDENTIFICATION GUIDE



COMMON FAILURE PATTERN EXPLANATIONS



TECH TIPS



EXCLUSIVE DORMAN COVERAGE

COOLANT RESERVOIRS



603-350 VW Beetle 2010-98

Pressurized

LOCATION

 Typically located along fender, in front of strut

COMMON REASON FOR FAILURE

- Crack in reservoir leading to loss of fluid and eventual engine overheating
- Cap failure (not releasing pressure or not properly attached)
- Collision damage

TECH TIPS

- Ensure fluid cools before
 opening cap
- Ensure level sensor is operating properly (if applicable)

Non-pressurized

FAILURES

coolant fluid

Damaged during

Collision damage

Ensure radiator is

only to cold level

operating properly

Ensure reservoir is filled

TECH TIPS

Located next to, or

attached to radiator; or radiator fan shroud

Use of fluids other than

replacement of other items

(radiator, radiator fan, etc.)

(AKA Overflow Bottle)

LOCATION



603-392 Chrysler Sebring, Dodge Stratus, 2005-01 Mitsubishi Eclipse 2005-98

POWER STEERING RESERVOIRS



603-934 2007-01 Chrysler Caravan, Grand Caravan, Town & Country, Voyager

LOCATION

Typically Located behind engine, next to or attached to Power Steering Pump



COMMON REASON FOR FAILURE

- Damaged during power steering pump removal
- Where applicable, o-rings deteriorate creating bad seal
- Where applicable, screen clogs with debris prohibiting free flow of fluid
- Collision damage

TECH TIPS

- Ensure proper seal to power steering pump
- · Ensure power steering pump is operating correctly

WINDSHIELD WASHER RESERVOIRS



603-159 Ford Explorer 2010-02, Lincoln Aviator 2005-03, Mercury Mountaineer 2010-02



LOCATION

• Typically located behind one of the headlights



- Use of fluids other than wiper fluid
- Road debris puncturing bottle
- Cap may be cracked, missing or improvised as a result of regular DIY fluid maintenance
- Collision damage

TECH TIPS

- Always use Windshield Wiper Fluid. Water expands when frozen and may crack reservoir.
- · Some installations may require wheel and wheel well liner removal



FLUID RESERVOIR COVERAGE GUIDE



