

CARDONE™ ProTech®

Supporting Today's Vehicle Technician



GM "W" Body Calipers Seized

Application GM "W" body vehicles

Problem Corrosion causing the slider pin to seize in the caliper.

Cause The use of dissimilar metals in the original design results in corrosion in the caliper slider pin bore, causing the slider pin to seize.

Solution CARDONE caliper part numbers 18-4295, 18-4296, 18-4327 and 18-4328 have a redesigned slider pin and a new dust boot. The redesigned pins allows more high temperature synthetic lubricant to be retained in the slider pin bore, preventing the pin from seizing.

