

CARDONE™ ProTech®

Supporting Today's Vehicle Technician



GM Instrument Panel Cluster (IPC) Relearn

Application

GM vehicles with a digital instrument panel cluster (IPC).

Problem

Vehicle will not start after replacement IPC has been installed.

Solution

Follow the security system (PASSLOCK) AUTO LEARN procedure outlined below to enable the replacement IPC and the ECC to communicate and learn a new password:

1. Before replacing the ECC, document all existing Diagnostic Trouble Codes (DTC) prior to repair.
2. Place the ignition key in the ON position.
3. Using a suitable scan tool, clear all security system (PASSLOCK) and Powertrain DTCs.
4. Rotate the ignition key to the CRANK position (attempt to start the vehicle). The engine will attempt to start and stall. Leave the key in the ON position.
5. Wait 10 minutes. Observe the SECURITY light. The SECURITY light will flash for a few seconds and remain on for 10 minutes.
6. Turn the ignition key to the OFF position after the SECURITY light goes out. Wait for at least 30 seconds.
7. Repeat steps 4-7 two (2) more times. A new password is now ready to be communicated to the security system (PASSLOCK) sensor, IPC and ECC with the next ignition cycle (start attempt).
8. If the engine starts, the Password Auto Learn procedure is complete. If the engine fails to start, perform relearn procedure again.
9. Check for any DTCs. Repair as necessary and clear if present.

Note

Refer to your vehicle's service manual for detailed relearn procedures specific to your application.

Visit cardone.com for more details on Flash.

©2020 CARDONE Industries, Inc. ProTech® is a registered trademark owned by CARDONE Industries, Inc. CARDONE™ is a pending trademark registration owned by CARDONE Industries, Inc.

For other ProTech® publications, visit www.cardone.com