

A DORMAN EXCLUSIVE CATEGORY

**DORMAN**®

**OE SOLUTIONS**™



# FLUID RESERVOIRS COVERAGE GUIDE



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES

## LOOK INSIDE FOR:



COMPLETE RESERVOIR  
IDENTIFICATION GUIDE



COMMON FAILURE PATTERN  
EXPLANATIONS



TECH TIPS



EXCLUSIVE DORMAN  
COVERAGE

# COOLANT RESERVOIRS



**603-350**  
VW Beetle 2010-98

## Pressurized



### LOCATION

- Typically located along fender, in front of strut



### COMMON REASON FOR FAILURE

- Crack in reservoir leading to loss of fluid and eventual engine overheating
- Cap failure (not releasing pressure or not properly attached)
- Collision damage



### TECH TIPS

- Ensure fluid cools before opening cap
- Ensure level sensor is operating properly (if applicable)

## Non-pressurized (AKA Overflow Bottle)



### LOCATION

- Located next to, or attached to radiator; or radiator fan shroud



### FAILURES

- Use of fluids other than coolant fluid
- Damaged during replacement of other items (radiator, radiator fan, etc.)
- Collision damage



### TECH TIPS

- Ensure radiator is operating properly
- Ensure reservoir is filled only to cold level



**603-392**  
Chrysler Sebring, Dodge Stratus, 2005-01  
Mitsubishi Eclipse 2005-98

# POWER STEERING RESERVOIRS



**603-934**  
2007-01 Chrysler Caravan, Grand Caravan,  
Town & Country, Voyager



### LOCATION

- Typically Located behind engine, next to or attached to Power Steering Pump



### COMMON REASON FOR FAILURE

- Damaged during power steering pump removal
- Where applicable, o-rings deteriorate creating bad seal
- Where applicable, screen clogs with debris prohibiting free flow of fluid
- Collision damage



### TECH TIPS

- Ensure proper seal to power steering pump
- Ensure power steering pump is operating correctly

# WINDSHIELD WASHER RESERVOIRS



**603-159**  
Ford Explorer 2010-02, Lincoln Aviator 2005-03,  
Mercury Mountaineer 2010-02



### LOCATION

- Typically located behind one of the headlights




### COMMON REASON FOR FAILURE

- Use of fluids other than wiper fluid
- Road debris puncturing bottle
- Cap may be cracked, missing or improvised as a result of regular DIY fluid maintenance
- Collision damage



### TECH TIPS

- Always use Windshield Wiper Fluid. Water expands when frozen and may crack reservoir.
- Some installations may require wheel and wheel well liner removal



For Complete Fluid Reservoir Coverage,  
Visit [DormanProducts.com](http://DormanProducts.com)

# FLUID RESERVOIRS

## SUPERIOR COVERAGE

### WINDSHIELD WASHER RESERVOIRS



**73**  
MILLION

VEHICLES COVERED

### POWER STEERING RESERVOIRS



**24**  
MILLION

VEHICLES COVERED

### PRESSURIZED COOLANT RESERVOIRS



**63**  
MILLION

VEHICLES COVERED

### NON-PRESSURIZED COOLANT RESERVOIRS



**52**  
MILLION

VEHICLES COVERED

**224 SKUS COVERING OVER 212 MILLION VEHICLES**

### NEW PRESSURIZED COOLANT RESERVOIRS

Make	Model	Year	Dorman #
Chrysler	Avenger, 200	2013	<b>603-379</b>
Chrysler	300, Charger, Magnum	2010-06	<b>603-056</b>
Ford	Fusion, Milan	2011-10	<b>603-333</b>
Ford	Edge, MKX	2010-08	<b>603-353</b>
Ford	F Series Trucks, Expedition	2010-03	<b>603-028</b>
Ford	Mustang	2010-05	<b>603-051</b>
Ford	Grand Marquis, Crown Victoria, Town Car	2011-98	<b>603-050</b>
Ford	Explorer	2005-02	<b>603-070</b>
GM	Cruze	2013	<b>603-383</b>
GM	Intrigue	2002-00	<b>603-143</b>
GM	Malibu, Pontiac G6	2006-04	<b>603-066</b>
GM	Malibu, Pontiac G6	2012-06	<b>603-067</b>
GM	Saturn Vue	2007-02	<b>603-238</b>
GM	LaCrosse, Regal, Cadillac SRX	2012-10	<b>603-228</b>
GM	Concours, Deville, Eldorado, Seville	2002-94	<b>603-133</b>
VW	Jett, GTI, EOS, A3, TT, TT Quattro, Passat, R32, Rabbit, Tiguan	2012-05	<b>603-253</b>

**For complete Fluid Reservoir coverage, visit [DormanProducts.com](http://DormanProducts.com)**



74187\_FluidReservoirCoverageGuide

Dorman Products, Inc. | 3400 East Walnut Street | Colmar, PA 18915  
Corporate Office and Customer Service: 1-800-523-2492  
New Product Idea Hotline: 1-800-336-3575

©2014 No reproduction in whole or in part without prior written approval.



[www.DormanProducts.com](http://www.DormanProducts.com)