

# GF4436B

## NOTICE

Due to a change in coil design by O.E., the practice of packing hold-down screws with the distributor cap has been discontinued. Since the new coil laminations are thinner, the use of the old-style, longer screw, with the new style coil, will result in a cracked cap or penetration of the screw through the cap. Hold-down screws are now packed with the coil to make sure of the proper match-up.

## AVIS

Comme la conception de la bobine d'équipement d'origine a été modifiée, les vis de retenue ne sont dorénavant plus comprises dans l'emballage du chapeau d'allumeur. Étant donné la nouvelle structure lamellaire plus mince de la bobine, les anciennes vis plus longues risqueraient de fissurer ou de perforer le chapeau d'allumeur. Les vis de retenue sont maintenant emballées avec la bobine de manière à ce qu'elle soient parfaitement assorties à celle-ci.

## AVISO

Debido al cambio en el diseño de la bobina realizado por el fabricante del equipo original, se ha descontinuado la práctica de suministrar tornillos de sujeción con la tapa del distribuidor. Como las láminas de la nueva bobina son más delgadas, usar los tornillos antiguos más largos con el nuevo estilo de bobina hará que se agriete la tapa o que estos penetren a través de la tapa. En lugar de ello ahora se suministran tornillos de sujeción con la bobina para asegurarse que sean compatibles.