

ATTENTION: Refer to the appropriate shop manual for your vehicle to obtain specific service procedures for this part. If you do not have a service manual or lack the skill to install this part, it is recommended that you seek the services of a qualified technician. Pay special attention to all cautions and warnings included in the shop manual. Read and follow all instructions carefully.

Various Models 1965–98

The distance between holes is approximately 66mm.


Some original equipment motors that these replace may have a distance of approximately 62mm.



Many OEM & replacement regulators have an elongated third hole that will accept motors with either the 62mm or the 66mm measurement.

If this hole is not elongated on the regulator you are working with simply elongate the hole with a file or rotary tool to interface with the motor correctly.

Elongate this hole with a file or rotary tool.



Disclaimer:

Even though every attempt is made to ensure this information is complete and accurate, it is impossible to account for all possible circumstances or situations. Please consult with a qualified auto technician before attempting to perform any work you are not qualified to do. Automobiles can be hazardous to work on; be sure to take all necessary safety precautions. Failure to do so may result in property damage or personal injury. Certain motor vehicle standards and performance requirements may apply to your motor vehicle (such as Federal Motor Vehicle Safety Standards by the National Highway Traffic Safety Administration). Be sure that your work is performed in accordance with such standards and that you do not disable any motor vehicle safety feature.