


# CHRYSLER ENGINE OIL FILTER BYPASS VALVE

NEW

## ORIGINAL ASSEMBLY



bypass valve  
located inside  
housing

## OE PROBLEM:

The Dealers only repair option for a failed original bypass valve is the complete replacement of the entire assembly



917-992

Chrysler 200/300, Town and Country 2013-11; Dodge Avenger, Challenger, Charger, Durango, Grand Caravan, Journey 2013-11; Jeep Grand Cherokee, Wrangler 2013-11; Ram 1500, C/V 2012-12

Pop Code: A | VIO: 1,869,121



- Dorman's Engine Oil Filter Bypass Valve enables replacement of only the failed original valve, without the need to replace the entire assembly, saving shop time and money

## FAILURE MODE:

- Original valve breaks inside oil filter housing and eventually leads to improper oil filtration