

# DORMAN HEATER HOSE ASSEMBLIES



## OUR UPGRADED PARTS OFFER TRUE DURABILITY

Heater hose assemblies are exposed to harsh conditions, often causing inferior plastic materials to become brittle and crack. Especially in more complex, multi-piece assemblies, you need more durable replacements to ensure a reliable repair. That's where Dorman expertise makes all the difference.

Focusing on complex heater hose assemblies, we rigorously engineer our solutions to endure even the most unforgiving underhood conditions. Many of our Dorman OE FIX solutions feature upgraded metal connectors to help prevent future failures—and it's all backed by our limited lifetime warranty.



## QUALITY COMPONENTS FROM THE AFTERMARKET'S MOST TRUSTED NAME

**Built to last** – Switch out failure-prone plastic parts for durable metal components.

**Seamless replacements** – Expect original fit and function of the OE on more complex designs.

**Superior engineering** – Discover reliable, upgraded replacements for complex heater hose repairs.

**Lifetime warranty** – Every Dorman component stands the test of time—you can count on it.



# DORMAN HEATER HOSE ASSEMBLIES

## FEATURED SOLUTIONS

As the following two examples show, Dorman's exclusive OE FIX heater hose assemblies feature design innovations—and upgraded materials—to resolve known flaws in original equipment and maximize service life. There are dozens of these superior heater hose designs in our industry-leading inventory.

### Improved Designs



REDESIGNED WITH  
A MORE DURABLE  
CONNECTOR TO RESIST  
CRACKING AND LEAKING

**626-609**  
Chevrolet Cruze 2016-11,  
Chevrolet Cruze Limited 2016

**PROBLEM:**  
Brittle factory connector  
cracks and leaks over time.

**FIX:**  
Redesigned mating  
connector provides a  
more secure connection  
to the water outlet for  
a longer service life

### Upgraded Material



FEATURES ALUMINUM  
Y-CONNECTORS FOR  
ADDED DURABILITY

**626-315HP**  
Chrysler Town & Country 2016-  
11, Dodge Grand Caravan 2020-11



**626-541**  
Ford F-150 2018-11,  
Ford Lobo 2018-11,  
Ford Mustang 2018-11,  
Lincoln Mark LT 2014-11

**PROBLEM:**  
Original equipment HVAC  
heater hose assemblies  
often fail due to cracks in  
the plastic Y-connector.

**FIX:**  
These Dorman OE FIX  
replacements feature  
upgraded aluminum  
Y-connectors to prevent  
similar failures in the future.



Get vehicle applications and technical details at [dormanproducts.com](http://dormanproducts.com)

Dorman Products, Inc. | Corporate Office and Customer Service: 1-800-523-2492 | Tech Line: 1-866-933-2911  
©2021 No reproduction in whole or in part without prior written approval.

Heater Hose Assembly\_Sell Sheet\_845301844