

FRONT IMPACT SENSORS

Also known as Air Bag Sensors

The Most Comprehensive Coverage
in the Aftermarket



590-200

Avalanche, Escalade, Sierra,
Silverado, Suburban, Tahoe, Yukon
2006-05

**15 SKUs Covering
Over 13 Million Vehicles
in Operation Today**



Located behind front bumper
on radiator support beam

- Easy to Install:
 - Direct fit replacements
 - Plug-and-play design
- Popular collision replacement category



**SCAN QR CODE TO VIEW
FRONT IMPACT SENSOR
VIDEO**

OR VISIT
www.YouTube.com/DormanProducts



Failure Mode:

Front Impact Sensors are sensitive to moisture and temperature fluctuations, and typically fail due to corrosion. When corrosion occurs, circuit board may become damaged leading to failure and illumination of airbag warning light.

FRONT IMPACT SENSORS

Also known as Air Bag Sensors

The Most Comprehensive Coverage
in the Aftermarket

COMPLETE FRONT IMPACT SENSOR COVERAGE

DORMAN #	APPLICATIONS	OE NUMBER
590-200	Avalanche, Escalade, Sierra, Silverado, Suburban, Tahoe, Yukon 2007-05	10370149
590-201	Express, Savana 2007-05	10371101
590-202	Avalanche, Escalade, Sierra, Silverado, Suburban, Tahoe, Yukon 2004-03	15057506
590-203	Avalanche, Escalade, Suburban, Tahoe, Yukon 2008-07	15854647
590-204	Sierra, Silverado 2007-05	10370150
590-205	Sierra, Silverado 2004-03	15057507
590-206	Sierra, Silverado 2008-07	15297468
590-207	Express, Savana 2004-03	15750627
590-208	Equinox 2006-05, Torrent 2006	10373058
590-209	Canyon, Colorado 2008-04	15779005
590-210	LaCrosse 2007-05	10372781
590-211	Bonneville, LeSabre 2005	25764117
590-212	Montana, Relay, Terraza, Uplander, Venture 2008-05	10363046
590-213	Envoy, Trailblazer 2004-02	15085679
590-214	Sierra, Silverado 2002-01	15070580

For Detailed Applications,
visit www.DormanProducts.com



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES



New Product Idea Hotline: 1-800-336-3575
www.DormanProducts.com

