

DORMAN EXCLUSIVE CATEGORY!

**24
SKUS**

Covering Over 35 Million Repair Opportunities



425-176
GM
2007-99



425-136
Impala
2005-00

PROBLEM:
OE Splined shaft design wears rapidly resulting in noise and binding.

SOLUTION:

DORMAN
Engineered

Long-life Double-D design smoothly transmits steering input without the annoying clunking.

Failure Mode:

- Clunking and/or binding in the Steering Column
- Failure results in the inability to steer properly

ALSO AVAILABLE:



425-161
Cobalt 2009-05,
G5 2009-07, Ion 2007-03



425-257
Dakota 2004-01
Durango 2003-01



425-455
Avalon 1999-95,
Camry, ES, 1996-92

APPLICATION GUIDE*

MAKE/MODEL	YEAR	DORMAN #
BUICK		
Century, Regal	2004-97	425-135
LaCrosse	2009-05	425-169
LeSabre, Lucerne	2008-00	425-154
CADILLAC		
DeVille, DTS, Seville	2008-00	425-154
CHEVROLET		
Cavalier	2005-95	425-137
Cobalt	2009-05	425-161
Equinox	2006-05	425-153
Impala	2010-06	425-158
Impala	2005-00	425-136
Monte Carlo	2007-06	425-155
Monte Carlo	2005-00	425-135
CHRYSLER		
Dakota, Durango	2004-01	425-257
Dakota, Durango	1999-97	425-263
Ram Pickup, Ram Van, Ram-charger	1993-78	425-253
Ram Pickup, Ramcharger, Trailduster	1987-79	425-252
FORD		
E Series Van	2012-97	425-352
GM		
Avalanche, Escalade, H2, Sierra, Silverado, Suburban, Tahoe, Yukon	2012-07	425-183
Avalanche, Escalade, H2, Sierra, Silverado, Suburban, Tahoe, Yukon	2007-99	425-176

MAKE/MODEL	YEAR	DORMAN #
KIA		
Sedona	2006-02	425-800
OLDSMOBILE		
Aurora	2003-01	425-154
Intigue	2002-98	425-135
PONTIAC		
Bonneville	2005-00	425-154
G5	2009-07	425-161
Grand Prix	2008-04	425-155
Grand Prix	2003-97	425-135
Sunfire	2005-95	425-137
Torrent	2006	425-153
SATURN		
Ion	2009-03	425-161
Vue	2007-02	425-153
TOYOTA		
Avalon, Camry, ES	1999-92	425-455
Avalon, Camry, ES, Solara	2012-02	425-454
Camry, ES	2001-97	425-458
Highlander	2006-04	425-463
Sienna, AWD	2010-04	425-461
Sienna, FWD	2010-04	425-462

*** For Complete Steering Shaft Coverage, Visit DormanProducts.com**



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES



New Product Idea Hotline: 1-800-336-3575
www.DormanProducts.com

