


DORMAN WINDOW REGULATORS



748-508
Chrysler Town & Country 2016-08,
Dodge Grand Caravan 2019-08,
Ram C/V 2015-12



748-542
Ford Expedition 2017-07,
Lincoln Navigator 2017-07

THE ORIGINAL ALTERNATIVE TO ORIGINAL EQUIPMENT

Dorman pioneered aftermarket window regulators and we continue to develop, design and deliver thousands of road-proven solutions today. Several of our exclusive designs feature unique and innovative improvements, all of which have been thoroughly tested to industry and regulatory standards. Backed by a team of in-house engineers, Dorman window regulators are built for long-term performance and reliability to get the job done right the first time.

3,000+
SOLUTIONS
WITH MORE EVERY MONTH

FMVSS compliant – Unlike some aftermarket competitors, all Dorman window regulators are designed to meet Federal Motor Vehicle Safety Standards for reliability and safety

Rigorously tested – State-of-the-art testing lab in Colmar, Pennsylvania, helps ensure fit, performance and long-term reliability



Exclusive plug-and-play designs – Millions of dollars invested in circuit board design and embedded technology leads to replacements that match OEM functionality



**CHECK OUT OUR
COMPETITOR
COMPARISON VIDEO**



FEATURED OE FIX™ WINDOW REGULATORS



741-644

Cadillac 2006-02, Chevrolet 2007-99, GMC 2007-99



The original equipment window regulator fails when the cable stresses over time. This Dorman OE FIX™ replacement **features added cable guides and sheathing** to counteract elongation and resist reel binding.



741-586

Ford E-Series 2019-02



The original equipment window regulator is riveted in place and requires a specialized rivet gun to replace. This Dorman OE FIX™ replacement **uses threaded hardware** to speed up the installation process, saving time and money.



741-348

Nissan Frontier 2015-05, Nissan Pathfinder 2010-05, Nissan Xterra 2015-05, Suzuki Equator 2010-09

The original equipment window regulator fails when the cable binds because it has poor tension. This Dorman OE FIX™ replacement regulator **incorporates cable tension springs** to resist cable reel binding.



748-974

Chevrolet Cruze 2015-10, Chevrolet Cruze Limited 2016

The original equipment window regulator fails when the plastic window slide block fatigues and cracks. This Dorman OE FIX™ replacement motor and regulator assembly **incorporates a redesigned slide block** for significantly greater durability.



Get vehicle applications and technical details at dormanproducts.com

Dorman Products, Inc. | Corporate Office and Customer Service: 1-800-523-2492 | Tech Line: 1-866-933-2911

©2021 No reproduction in whole or in part without prior written approval.

Window-Regulators-2021-Campaign_Sell-Sheet_DOR630186717