







409S[®] Stainless Steel

Installation diagram for:
SYSTEM #81071
2 1/2" MANIFOLD DOWNPIPES
1964-77 BIG BLOCK CHEVROLET VEHICLES
NOT FOR USE WITH HEAT RISER VALVE



HARDWARE INCLUDED:

		
SF012 (2)	GA108 (2)	TB515S (2)