

CARDONE™ ProTech®

Supporting Today's Vehicle Technician



Troubleshooting Chrysler Power Steering Gear Boxes

Application

Chrysler vehicles 1962-1972 (27-6546), 1975-1988 (27-6542)

Problem

Whine or growl noises.
Poor steering return.
Hard steering or lack of assist.
Binding in steering or leakage.

Cause

Sticking Power Piston or
restriction in Control Valve Body.

Solution

Disassemble *Control Valve Body*.
Clean & inspect all parts. Flush
system thoroughly and bleed
according to manufacturers
specifications.

NOTE: Control Valve body
may not be supplied with
your replacement gear box.
Do not transfer part until
thoroughly flushed

Note

**Do not tamper with steering
valve body, this is pre-set at
the factory.**

