

CARDONE™ ProTech®

Supporting Today's Vehicle Technician




Don't Get Power Cylinder or Control Valve Hoses Crossed

Application All linkage-type Power Steering Systems

Problem After replacing the power steering unit, the vehicle steers violently from side to side by itself.

Solution When installing a control valve or power cylinder, be extremely careful not to cross the pressure lines to the cylinder. Failure to do so can lead to a malfunction and could result in bodily injury and VOID WARRANTY.



Caution When replacing any part in the power steering system, ALWAYS FLUSH THE SYSTEM USING APPROVED POWER STEERING FLUID AND REPLACE HOSES! New parts can become contaminated with residues from existing components possibly causing malfunctions.