

CARDONE[™] ProTech[®]

Supporting Today's Vehicle Technician



Dodge and Jeep Trucks Pulley/Hub ID Guide 1992-97

Application

Dodge trucks 1992 using 58-447 or 58-559. Dodge and Jeep trucks 1997-93 using 58-481 or 58-560.

Problem

Replacement unit has a bolt on pulley. The original unit has a press on pulley.

Cause

Mid-year design change by the OEM.

Solution

CARDONE[™] is now supplying this pump with a press on pulley. The new part numbers are 58-559 and 58-560.

Pump with bolt on pulley

58-447 outlet threaded
58-481 outlet not threaded



Pump with press on pulley

58-559 outlet threaded
58-560 outlet not threaded

