


Chrysler CV ID Guide

Application Chrysler front wheel drive axles.

Problem CV driveaxle replacement units are different.

Cause Chrysler uses four different design joints.

Solution All four designs are interchangeable as long as the complete axle is installed.



Note

Chrysler CV axles MUST be handled with extreme caution! The inboard joint is spring loaded and may pop loose, causing a total malfunction and VOID THE WARRANTY.

©2020 CARDONE Industries, Inc. ProTech® is a registered trademark owned by CARDONE Industries, Inc. CARDONE™ is a pending trademark registration owned by CARDONE Industries, Inc.

MS8166 PT60-0003