

CARDONE™ ProTech®

Supporting Today's Vehicle Technician



VCI – Vehicle Calibration Information

Application

GM vehicles with Flash technology, 1996 and newer.

Problem

- Calibration codes for valid flash PCM's missing from AC Delco TIS2Web site.
- VCI option removed from the TIS2Web site.

Solution

Contact AC Delco Customer Support Center (see the AC Delco web site for current contact information) to request the posting of a missing calibration or to request a VCI number. The following information should accompany your request:

- Your valid TIS2Web account user name
- Reason for your request (missing calibration or desired modification)
- Any flash error codes
- Vehicle VIN number
- Year, make and model
- PCM OEM service number
- Other info as requested

Note

Please refer to your vehicle's service manual for specific diagnostic instructions. This ProTech bulletin is supplied as technical information only and is not an authorization for repair.