



624-650

TRANSMISSION BYPASS VALVE

NEED HELP?

Please call our Technical Support team for assistance from our team of certified automotive experts.

1-866-933-2911



Threaded service port
Puerto de servicio roscado
Port de service fileté

ENGLISH

This new transmission bypass valve includes a change from the OE design. A threaded service port has been added to the valve access in place of the original equipment snap ring to shield the valve's bore from contaminants.

ESPAÑOL

Esta nueva válvula de derivación de la transmisión incluye un cambio con respecto al diseño del equipo original. Se agregó un puerto de servicio roscado al puerto de la válvula en lugar del anillo de retención del equipo original para proteger el orificio de la válvula de contaminantes.

FRANÇAIS

Cette nouvelle vanne de dérivation pour transmission comprend un changement par rapport à la conception d'origine. Un port de service fileté a été ajouté au port de la vanne à la place de la bague de retenue de l'équipement d'origine pour protéger l'alésage de la vanne des contaminants.