

EXCLUSIVE AFTERMARKET OFFERINGS

**180
SKUS**

Covering Over
180 Million Vehicles!

Generates an electrical signal proportional to the wheel speed used by the ABS control unit to prevent brakes from locking during vehicle braking

DIRECT FIT

- Matches OE fit, form & function
- Extensive coverage for both domestic and import application



970-040

General Motors 2012-00




970-094

Chevrolet Colorado GMC
Canyon 2008-04



970-024

Dodge 2005-98



970-098

S10 2003-91
Sonoma 2003-95 FR



970-053

Cadillac 2012-07,
GMC 2012-07



Failure Mode:

- Brake dust, metallic debris and dirt foul up tone wheel and sensor hear
- Environmental exposure degrades sensor, wiring or connector
- A failing sensor can illuminate the MIL or ABS warning lamp, causing the vehicle to disable the anti-lock braking system

**To find complete application coverage
visit www.DormanProducts.com**

ADDITIONAL APPLICATION COVERAGE*

Part No.	Application
970-012	Dodge 1997-90, Ford 2009-90, Lincoln 2002-98, Mazda 2009-91, Mercury 2001-97
970-011	Cadillac 2006-02, Chevrolet 2012-99, GMC 2012-99, Hummer 2007-03
970-040	GENERAL MOTORS 2012-00
695-225	Ford 2012-04, Lincoln 2008-06
970-024	Dodge 2005-98
970-353	Cadillac 2012-07, Chevrolet 2012-07, GMC 2012-07
970-081	Lexus ES300 2001-97, Toyota Avalon 2005-95, Toyota Camry 2001-92, Toyota Solara 2003-99
970-080	Lexus ES300 2001-97, Toyota Avalon 2004-95, Toyota Camry 2001-92, Toyota Solara 2003-99
970-002	Buick 1998-91, Cadillac 1999-97, Chevrolet 2005-92, Oldsmobile 1998-91, Pontiac 2005-91
970-001	Buick 1997-91, Cadillac 1999-97, Chevrolet 2005-92, Oldsmobile 1998-92, Pontiac 2005-91
970-008	Chevrolet 2005-97, Oldsmobile 2004-97, Pontiac 2005-99
970-009	Chevrolet 2005-97, Oldsmobile 2004-97, Pontiac 2005-99
970-281	Ford 2009-98, Mazda 2009-98, Mercury 2001-98
970-034	Lexus ES300 2001-97, Toyota Avalon 2004-97, Toyota Camry 2001-97, Toyota Solara 2003-99
970-035	Lexus ES300 2001-97, Toyota Avalon 2004-97, Toyota Camry 2001-97, Toyota Solara 2003-99
970-022	Ford 2009-95, Mazda 2009-00, Mercury 2001-97
970-238	Ford 2004-97, Lincoln 2002-98

Also Available

Camshaft and Crankshaft Coverage

Part No.	Part Description	Applications
917-709	Cam Position Sensor	Chrysler 2009-07, Dodge 2010-00, Jeep 2009-99
917-724	Cam Position Sensor	General Motors 2007-97, SAAB 2005
917-751	Crankshaft Sensor	Ford 2013-92, Lincoln 2013-91, Mercury 2011-92
917-754	Crankshaft Sensor	Ford 2008-98, Mercury 2007-98
917-781	Crankshaft Sensor	Infiniti 2010-02, Nissan 2012-02

Vehicle Speed Sensors

Part No.	Part Description	Applications
917-615	Vehicle Speed Sensor	GENERAL MOTORS 2011-96, GENERAL MOTORS 1994-92, ISUZU 2008-03
917-618	Vehicle Speed Sensor	GENERAL MOTORS 2011-98, ISUZU 2008-03, SAAB 2009-05
917-603	Trans Speed Sensor	Lexus 2009-92, Scion 2011-05, Toyota 2009-93

***To find complete application coverage visit www.DormanProducts.com**



NUEVOS PRODUCTOS • NUEVAS SOLUCIONES • NUEVAS OPORTUNIDADES

DORMAN[®]
NEW SINCE 1918

Dorman Products, Inc.
3400 East Walnut Street | Colmar, PA 18915
Servicio al cliente corporativo y de oficina: 1.800.523.2492

Nueva línea de Soporte Técnico para México: 001 800 868 5777
www.DormanProducts.mx

**SEA EL PRIMERO
EN SABER**
ACERCA DE PARTES
"ANTERIORMENTE SÓLO DE AGENCIA"

© 2014 No hay reproducciones en su totalidad o en parte, sin la aprobación previa por escrito.

75149 | 20140701