



27-8418: 1 or 2 Piece Casting?

Application

2002-2020 Chevy Avalanche, Express 2500, Express 3500, Express 4500, Silverado 1500HD, Silverado 2500& 2500HD, Silverado 3500& 3500HD, Suburban 2500. GMC Savannah 2500, Savannah 3500. Savannah 4500, Sierra 1500HD, Sierra 2500& 2500HD, Sierra 3500& 3500HD, and Yukon XL2500.

Problem

Replacement unit does not look like the O.E. steering gear.

Cause

This unit can be supplied two different ways.

Solution

27-8418 can come as a one piece or a two piece casting. The two steering gears will look different in appearance, but O.E. fit and functionality will remain the same. Simply install the replacement unit using the O.E. procedure.

1 PIECE CASTING



2 PIECE CASTING

