



27-7616 Mounting Bolt Kit Differences

Application 2006-2008 Dodge Ram 1500, 2500, 3500, & 4000

Problem The mounting hole sizes on the replacement gearbox do not match the original and the original bolts cannot be reused.

Cause There are two versions of P/N 27-7616 which we supply. One version will have 7/16x14 standard mounting hole threads. The second version will have 14x2.0 metric mounting hole threads.

Solution New mounting bolts are supplied for gears that require the 7/16x14 adapted bolt kit. Use the bolts supplied with replacement steering gear for proper fitment. A bushing kit will also be supplied with units that have the 7/16x14 mounting bolts to compensate for the larger pass-through holes in the vehicle's frame.

Adapted 7/16 x 14 bolt kit w/bushings



O.E. 14mm x 2.0 bolts

