

Relocating Power Steering Hose May Eliminate Vibration


Application All power steering equipped vehicles.

Problem Power steering noise.

Solution

Cause Power steering pressure hoses vibrate under high pressure. Hoses may be contacting the body, frame or engine oil pan causing noisy operation.

Relocate the power steering hoses. Check for missing hold down clamps or hardware. Replace damaged hoses as necessary.



Note Failure to flush system will **VOID THE WARRANTY**.

©2020 CARDONE Industries, Inc. ProTech® is a registered trademark owned by CARDONE Industries, Inc. CARDONE™ is a pending trademark registration owned by CARDONE Industries, Inc.

JDA5235 PT20-0010